



Corrigenda

Installation Guide contain incorrect descriptions. Refer to the following table and confirm the descriptions that are corrected.



WV-X1571LN / WV-X1551LN / WV-X2571LN / WV-X2551LN / WV-S1572L / WV-S1552L / WV-S2572L / WV-S2552L / WV-X4573L / WV-S4551L / WV-X4573LM / WV-S4551LM

Making connections

| Incorrect | Correct |
|---|--|
|  <p>Audio input cable (white)</p> <p>Less than <u>10 m {32.8 feet}</u> (for microphone input)</p> <p>Less than <u>1 m {3.28 feet}</u> (for line input)</p> |  <p>Audio input cable (white)</p> <p>Less than <u>1 m {3.28 feet}</u> (for microphone input)</p> <p>Less than <u>10 m {32.8 feet}</u> (for line input)</p> |

WV-X4173 / WV-S4151 / WV-X4172 / WV-X4573L / WV-S4551L / WV-X4573LM / WV-S4551LM

Processing the installation surface (process according to the installation type)

| Incorrect | Correct |
|--|---|
|  |  |

WV-X4173 / WV-S4151 / WV-X4172

Optional accessories

| Incorrect | Correct |
|---------------------------------|----------------------------------|
| Corner mount bracket : WV-Q105A | Ceiling mount bracket : WV-Q105A |

* PGQW2317ZA *




avs0121-0
Printed in China

正誤表

取扱説明書 設置編に記載の誤りがありました。以下に正しい内容を記載します。

WV-X1571LNJ / WV-X1534LNJ / WV-X2571LNJ / WV-X2533LNJ /
 WV-S1572LNJ / WV-S1552LNJ / WV-S2572LNJ / WV-S2552LNJ /
 WV-X4573LJ / WV-S4551LJ

接続する



WV-X4173J / WV-S4151J / WV-X4573LJ / WV-S4551LJ

設置面を加工する (取付タイプに合わせて加工する)

